










Montageanleitung Bürostuhl ExtraComfortAlu

NO.	Parts List	Q'ty
①		X1
②		X1
③		X1
④		X1
⑤		X1 Pair
⑥		X1
⑦	 M6X25	X8
⑧	 M8X16	X3



www.sitzstetisch.com